

This Page Is Inserted by IFW Operations
and is not a part of the Official Record.

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Appln No. 10/727,180
Amdt. Dated May 19, 2004
Preliminary Amendment

2

Amendments to the Specification:

The paragraph beginning at Page 10, please insert new line 30 as follows:

Figure 63A Timers sub-block partition diagram

The paragraph beginning at Page 10, please insert new line 32 as follows:

Figure 66 is a schematic of a timing pulse generator

The paragraph beginning at Page 16, line 5, to be amended as follows:

Figure 278 is intentionally omitted shows power on reset

The paragraph beginning at Page 18, line 39 to be amended as follows:

Figure 388A shows setup for multiple preauth fields

Appln No. 10/727,180
Amdt. Dated May 19, 2004
Preliminary Amendment

3

Amendments to the Drawings:

Please delete Figure 413 on page 331 of the drawings and insert Figure 278 on page 237 of the drawings.